

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

AT232  
SSE  
1/4-1/2  
0.352 mi.  
1858 ft.

TM 1062  
W 8TH ST /SURF AVE  
BROOKLYN, NY  
Site 3 of 10 in cluster AT

NY Spills S104651694  
N/A

Relative:  
Higher

Actual:  
3 ft.

SPILLS:

Name: TM 1062  
Address: W 8TH ST /SURF AVE  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0000382 / 2002-01-17  
Facility ID: 0000382  
Facility Type: ER  
DER Facility ID: 252035  
Site ID: 312575  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2000-04-10  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 2000-04-10  
CID: 389  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2000-04-10  
Spill Record Last Update: 2002-01-23  
Spiller Name: Not reported  
Spiller Company: UNK  
Spiller Address: UNKNOWN  
Spiller Company: 999  
Contact Name: CALLER  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was O'CONNELL Con Ed e2mis #130822 Notes: 4-10-00 Undiaperable sheen on 400gal water in TM 1062. Sample taken. 1945hrs LSN 00-03494 <1ppm PCB 4-11-00 1720hrs Cleanup complete. Double washed with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump."

Remarks: "caller reporting a spil of material in a transformer manhole samples aken clean up pending lab results coned#130831 no callback necessary"

All Materials:

Site ID: 312575  
Operable Unit ID: 822155  
Operable Unit: 01  
Material ID: 288631  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Oxygenate:

Not reported